









## כיצד לבחור פס נחושת אלקטרוניטי

זרם עבודה								מפתח פריט	AxE מ"מ
טמפרטורת עבודה 65°C				טמפרטורת עבודה 85°C					
									
			160				212		12x4
			183				241		12x5
			274				363	70090-2	20x5
		586	327			776	433		25x5
1003	896	672	379	1329	1187	890	502	70090-3	30x5
1220	1090	836	482	1617	1444	1108	639	70090-4	40x5
1411	1260	994	583	1870	1670	1317	772	70090-5	50x5
1613	1440	1150	688	2137	1908	1524	912	70090-6	60x5
1673	1494	1197	718	2217	1980	1586	951		63x5
1960	1750	1450	885	2597	2319	1921	1173	70090-7	80x5
2296	2050	1730	1080	3042	2716	2292	1431		100x5
2666	2381	2022	1300	3532	3155	2679	1723		125x5
1547	1289	986	573	2041	1701	1300	756	70095-1	30x10
1931	1609	1230	715	2549	2124	1624	944	70095-2	40x10
	2040	1510	852		2703	2001	1129	70095-3	50x10
	2300	1720	985		3048	2279	1305	70095-4	60x10
	2790	2110	1240		3697	2796	1643	70095-5	80x10
	3260	2480	1490		4320	3286	1974	70095-6	100x10
	3740	2860	1740		4956	3790	2306	70095-7	120x10
	4680	3590	2220		6201	4757	2942		160x10
	5610	4310	2690		7433	5711	3564		200x10